

Part 5: Areas inspected

Preparation area, filling area, packaging areas, warehouses, AHUs, laboratories, water treatment station, compressed air generator.

Part 6: Description

1- Preparation area, filling area, packaging area, utilities, water treatment station

The facility shows compliance to GMP guidelines regarding:

- Suitable layout showing logic process flow.
- The factory premises shows adequate spaces.
- Classification and differential pressure were revised and were found complying.
- Suitable equipment used in manufacturing process.
- Facility was kept clean and had adequate lighting, ventilation, and environmental control.
- Area and equipment documentations and qualification were revised.
- Area supplies qualifications were revised and found complying.

2- Warehouse

- Adequate spaces and segregation of quarantine and released for raw materials, finished products, packaging materials was present.
- Warehouses were found in a good cleanliness state with adequate lighting, ventilation.

3- Laboratories

- Laboratories premises layout was designed to suit the operations to be carried out.
- Appropriate calibrated equipment was present.
- Sufficient space was provided

Part 7: References

- As per the law 151 for year 2019 of “promulgating law establishing the Egyptian authority for unified procurement, medical supply and technology management (AUPP) and Egyptian drug Authority (EDA) article 17 which stated “EDA shall exercise all regulatoryaccording to international standards”.
- Also, as per prime minister degree no.777 for year 2020 article 17 which stated “...EDA adoption of standards and requirements of world health organization for the norms and requirements of good manufacturing practice (GMP).
- And all with taking into considerations the WHO references listed in the following link:

<https://www.edaegypt.gov.eg/ar/%D8%A7%D9%84%D9%82%D9%88%D8%A7%D9%86%D9%8A%D9%86-%D9%88%D8%A7%D9%84%D9%82%D8%B1%D8%A7%D8%B1%D8%A7%D8%AA-%D9%88%D8%A7%D9%84%D9%82%D9%88%D8%A7%D8%B9%D8%AF-%D8%A7%D9%84%D9%85%D9%86%D8%B8%D9%85%D8%A9-%D9%88-%D8%A7%D9%84%D8%A5%D8%B4%D8%B9%D8%A7%D8%B1%D8%A7%D8%AA/%D8%A7%D9%84%D9%85%D8%AF%D9%88%D9%86%D8%A7%D8%AA-%D8%A7%D9%84%D9%85%D8%B1%D8%AC%D8%B9%D9%8A%D8%A9/>

Part 8: Conclusion & The licensing inspection committee final decision.

Conclusion:

- Based on the areas inspected, the people met, and the documents reviewed, there was an acceptable level of compliance regarding: Production Areas, Equipment, warehouses, laboratories reviewed documents.
- The comments observed during the first licensing inspection were listed in the complete licensing inspection report and were addressed by the manufacturer & almost all of the comments of the first licensing inspection were fulfilled and only six comments should be fulfilled from inspector of administration of inspection of pharmaceutical products factories for human, veterinary, herbal and disinfectants.

The licensing inspection committee final decision.

Granting the license